

Finch West Line 6 Delay Log Summary December 7-13, 2025							
Time	Location	Reason	Car	Change Off	Delay	Gap	Out of Service
	Sunday December 7 (Opening)						
7:29am	Finch West WB	Doors opened off platform. Operator error. (Ceremonial train)					
9:17am	Milvan Rumike WB	Traction fault code.	6501	N	7	17	
9:25am	Milvan Rumike EB	Brake fault. Resolved by remedial checks. Two trains short turned.	6512	N	5	15	
9:34am	Humber College EB	Multiple fault alarms. Resolved by technician.	6502	N	4	14	
9:55am	Humber College EB	Operator had to use washroom on mezzanine level due to platform level facilities being out of service.			5	15	
10:05am	Tobermory EB	Brake fault. Resolved by remedial checks.	6514	N	4	14	
10:10am	Finch West WB	Train held by technician. Reason unknown.	6502	N	15	25	
10:48am	Rowntree Mills WB	Brake fault. Resolved by remedial checks.	6517	N	5	15	
11:03am	Emery EB	Train removed from service by TTC.	6509	Y	10	20	
12:36pm	Norfinch Oakdale EB	Train removed from service.	6502	Y	10	20	
1:37pm	Emery WB	Train overshot platform. Braking issue.	6507	N	5	15	
2:54pm	Emery WB	Misaligned train. Emergency mode used.	6501	N	3	13	
3:30pm	Humber College	Power issues in station. Service not affected.					
4:16pm	Signet Arrow WB	Error code.	6512	N	3	10	
4:34pm	Sentinel WB	Misaligned train. Emergency mode used.	6508	N	3	13	
6:26pm	Pearldale WB	Power supply. Train OKed for service.	6514	N	13	23	
8:56pm	Martin Grove EB	Operator unable to maintain headway. One train short turned.	6512	N	12	24	
9:12pm	Humber College EB	Operator using facilities (see also 9:55am)			7	19	
9:59pm	Finch West WB	Operator unable to maintain schedule.			12	24	
11:05pm	Humber College EB	Loss of doors. Recycled OK.	6512	N			
	Monday December 8						
5:08am	Finch West WB	Late clearing work zone			14		
5:28am	Humber College EB	Operator not in position			6		
6:44am	Jane EB	Slow operation from hand-off			3	9	
6:46am	Jane WB	Overspeed indication causing emergency brake	6507	N			
6:55am	Martin Grove EB	Operator could not open doors and other problems. Turned back but took extended time.	6517	N	4	10	
8:10am	Humber College EB	Operator not in position			6	12	
9:41am	Humber College EB	Operator using facilities			5		
12:56pm	Rowntree Mills EB	Misaligned train. Emergency mode used.	6509	N	4	14	
1:11pm	Humber College EB	Removed from service â€“ mechanical issues. Repaired by technician.	6517	N	10	10	29

Finch West Line 6 Delay Log Summary December 7-13, 2025							
Time	Location	Reason	Car	Change Off	Delay	Gap	Out of Service
1:20pm	Humber College EB	Operator using facilities			4	10	
3:01pm	Jane EB	Late leaving yard. Confusion re crew.			4	14	
3:42pm	Sentinel EB	Heat issue in cab	6517	Y	6	12	113
4:41pm	Finch West WB	HVAC issues	6512	N	6	12	86
5:30pm	Albion WB	Circuit breaker	6511	N	3	9	
9:19pm	Driftwood EB	Brake problem; also delayed by tech unfamiliar with equipment.	6503	N	9	23	
10:33pm	MSF WB	Train caught on dead spot. Pushed clear.					181
Tuesday December 9							
5:06am	Norfinch Oakdale WB	Car posted a fault which cleared on its own.	6501	N			
7:16am	Norfinch Oakdale WB	Indicator lights defective. Cleared on its own.	6507	N			
7:42am	Signet Arrow WB	Car posted a fault which cleared on its own.	6514	N			
8:33am	Westmore WB	Car posted faults	6508	Y			
8:56am	Milvan Rumike EB	Car posted a fault which cleared on its own.	6514	N			
9:01am	Signet Arrow WB	Car posted a fault which cleared on its own.	6503	N			
9:12am	Humber College EB	One door not opening. Isolated.	6516	N	6	12	
1:05pm	Jane WB	Misalignment	6503	N	3	9	
1:34pm	Tobermory WB	Overspeed. Car reset and continued.	6509	N			
3:16pm	Humber College EB	Switch out of service. Repaired by tech. Service turned back at Martin Grove			92	98	
3:30pm	Martin Grove WB	Switch out of service. Repaired by tech. Service turned back at Mount Olive			45	51	
9:48pm	Driftwood WB	Unspecified operator issue			10	20	
10:23pm	Islington EB	Disabled train. Technician reset circuit breaker.	6513	N	32	42	
		Three storm trains operated to keep line clear.					
11:32pm	Finch West WB	Flat wheels on car. Deemed unsafe to operate.	6513	Y			
Wednesday December 10							
4:56am	Norfinch Oakdale WB	Car posted a fault which cleared on its own.	6517	N			
5:13am	Norfinch Oakdale WB	Car posted a fault which cleared on its own.	6503	N			
6:53am	Jane EB	Car posted a fault which cleared on its own.	6502	N			
7:25am	Jane EB	Radio issues. Repaired by tech.	6513	N	6	12	49
8:40am	Jane EB	Operator unable to maintain schedule. Unable to short turn service due to loss of control of switches.			15	21	
9:03am	Tobermory	Lost control of multiple switches. Repaired by tech.			15	21	
12:28pm	Humber College EB	Overspeed indication tripping emergency brake. Car reset and continued.	6504	N			

Finch West Line 6 Delay Log Summary December 7-13, 2025							
Time	Location	Reason	Car	Change Off	Delay	Gap	Out of Service
1:05pm	Duncanwoods EB	Loss of control of switches			5	15	
6:12pm	Humber College EB	Operator error			10	20	31
6:16pm	Stevenson EB	Auto broke down on rail. Unable to turn back service due to switches not working (weather).			6	12	
7:47pm	York Gate	Switch out of control. Trains rerouted.					
8:52pm	Emery EB	Car posted a fault. Car reset and proceeded.	6515	N			
9:18pm	Humber College EB	Loss of control of switches.			100	110	
9:30pm	Albion	Loss of control of switches. Service on Line 6 suspended.			100	110	
Thursday December 11							
5:19am	York Gate B/W	Switch failure			46	51	
6:21am	Humber College EB	Switch failure			93	105	
7:47am	Jane EB	No car available.			6	12	94
7:48am	Sentinel EB	Car posted a fault. Car reset and proceeded.	6501	N			
9:21am	Driftwood EB	Car posted a fault. Car reset and proceeded.	6506	N			
10:38am	Humber College EB	Emergency brake caused injury to staff on board.	6515	N			
11:30am	Humber College EB	Communications problem. Repaired by tech enroute.	6508	N	6	12	
3:07pm	Pearldale WB	Operator unable to maintain schedule due to excessive dwell time at stops.	6501		10	16	
3:22pm	Finch West WB	Screen blank. Repaired by mechanic. Car out of service for 116 minutes.	6517	N	6	12	
3:41pm	Jane EB	No car available.			6	12	199
6:21pm	Duncanwoods EB	Operator unable to maintain schedule. New operator unfamiliar with the line.	6508		15	21	
8:32pm	Duncanwoods EB	Operator unable to maintain schedule.	6506		15	25	
9:27pm	Jane WB	Emergency brake. Car reset.	6514	N			
10:25pm	Humber College EB	Car posted a fault. Car reset and proceeded.	6513	N			
Friday December 12							
5:10am	Jane EB	Emergency brake. Car reset and proceeded.	6506	N			
5:17am	Driftwood WB	Train routed incorrectly. Operator shut down and changed ends, but several errors posted due to pantograph down. Repaired by tech. Train changed off.	6515	Y	4	14	
5:52am	Stevenson WB	Emergency brake. Car reset and proceeded.	?	N	4	16	
5:56am	Humber College EB	Radio issues. Train changed off.	6508	Y	10		
7:25am	Jane EB	No car available.					180
7:47am	Jane EB	No car available.					107
8:00am	Finch West WB	Compressor issues. Repaired by tech.	6512	N	10	20	

Finch West Line 6 Delay Log Summary December 7-13, 2025							
Time	Location	Reason	Car	Change Off	Delay	Gap	Out of Service
8:08am	Martin Grove EB	Emergency brake. Car reset and proceeded.	6501	N	3	10	
8:11am	Finch West WB	Emergency brake due to circuit breaker problem. Car reset and proceeded.	6511				
8:40am	Signet Arrow EB	Unable to open doors.	6507	N	3	10	
8:45am	Jane WB	No heat. Train operated to yard.	6513	N	7	14	60
8:48am	York Gate WB	Switch issue. Repaired by tech.	6514		4	14	
9:08am	Finch West WB	No cab heat.	6507	Y	7	14	
11:05am	Humber College EB	Air compressor problem resolved by tech.	6512	N	10	20	
11:42am	Humber College EB	Operator issue (unspecified).	6512		10	20	160
1:07pm	Finch West WB	Mechanical issues, repaired by tech.	6515	N	10	20	
2:34pm	Humber College EB	No cab heat. Tech unable to repair. Changed off.	6512	Y	7	14	175
3:49pm	Jane EB	No car available.			7	14	204
5:26pm	Milvan Rumike EB	Unable to maintain schedule due to traffic signals, customers and icy rail. Operator new to the line.	6508	N	12	19	
5:55pm	Emery WB	Misalignment. Spin-slide occurred before stop.	6511	N	4	11	
6:00pm	Humber College EB	Car posted a fault. Car reset and proceeded.	6506	N	10	17	
6:06pm	Finch West WB	Overspeed. Car reset and proceeded.	6509	N	7	14	
9:04pm	Finch West WB	Sander problem. Car changed off.	6504	Y	7	12	
Saturday December 13							
5:41am	Norfinch-Oakdale EB	Fault code. Cleared on its own.	6511	N			
8:33am	Finch West WB	No heat in cab. Alstom techs had to shut down and restart train which then was detected as a "non communicating object" blocking movements through the crossover. Trains turned back west of Finch West and one operated a shuttle from Finch West to Driftwood.	6506	N	37		
11:35am	Tobermory WB	Emergency brake. Unable to release. Alstom tech performed remedial checks. Shuttle train service from Driftwood to Finch West.	6509	N	32	39	
12:31pm	Norfinch Oakdale WB	Overspeed. Operator reset.	6511	N			
12:52pm	Humber College EB	Operator using facilities. One train turned back from Martin Grove. One train advanced.	6509	N	17	27	
1:10pm	Finch West WB	Guideway intrusion detected during departure. Three trains turned back at Tobermory. Car would not come out of emergency mode.	6503	N	30	39	
1:14pm	Finch West WB	Error indication on truck. Reset by operator.	6503	N			
2:14pm	Norfinch Oakdale WB	Emergency brake. Cleared on its own.	6515	N			
3:42pm	Rowntree Mills EB	Fault code. Reset by operator.	6506	N	7	17	

Finch West Line 6 Delay Log Summary December 7-13, 2025							
Time	Location	Reason	Car	Change Off	Delay	Gap	Out of Service
4:07pm	Albion EB	Emergency brake, unable to reset.	6514	N	5	15	
4:37pm	Humber College EB	Emergency brake due to reopening doors. Operator reset.	6505	N			
4:43pm	Signet Arrow	Person running on guideway.	6508	N			
6:07pm	Driftwood EB	Fault code.	6501	N			
7:18pm	Sentinel WB	Overspeed.	6511	N			
8:43pm	Finch West WB	Door problem.	6508	N	4	14	
9:32pm	Albion WB	Operator locked keys in cab.	6508	N	6	18	

Finch West Line 6 Delay Log Summary December 14-20, 2025							
Time	Location	Reason	Car	Change Off	Delay	Gap	Out of Service
	Sunday December 14						
8:13am	Westmore EB	Unable to open doors. Emergency mode used.	6513	N	3	13	
8:22am	Jane EB	Cold cab.	6517	N	6	16	
8:31am	Approaching Rowntree Mills EB	Train disabled with seized brakes. Passengers off-loaded. 8 trains turned at Rowntree Mills, 6 at Duncanwoods, 1 at Albion.	6513	Y	119	129	136
10:26am	Milvan Rumike EB	Multiple error codes. Remedial checks run.	6517	N	3	13	
10:42am	Albion EB	Emergency brake activated. Remedial checks run.	6506	N	3	13	
12:01pm	Martin Grove WB	Emergency brake activated.	6514	N	3	13	
12:18pm	Sentinel WB	Emergency brake activated. Error cod major traction fault. Remedial checks resolved issue.	6501	N	5	15	
1:53pm	Humber College EB	Operator using washroom.	6514	N	5	10	
6:31pm	Jane WB	Error code. Resolved.	6514	N			
7:00pm	Milvan Rumike EB	Operator injured when top compartment fell while adjusting mirror. Replacement operator used. Following trains advanced.	6501	N			35
7:12pm	York Gate WB	Switch locked. Unlocked by following train.			12	24	
	Monday December 15						
7:53am	Jane WB	Error code displayed. Reset. Compounded by poor radio comms.	6505	N	4	7	
8:09am	Duncanwoods WB (entering)	Overspeed causing emergency braking.	6511	N			
8:50am	Finch West WB	Train held due to fault codes.	6515	N	4	8	
9:31am	Westmore EB (entering)	Overspeed causing emergency braking.	6516	N			
9:55am	Finch West WB	Operator using washroom. 1 train turned at Tobermory.	6503	N	5	9	
12:11pm	York Gate	Locked switch. No service delay.					
2:08pm	Stevenson EB	Train held. Reason unknown.	6504	N	7	17	
3:29pm	Pearldale EB	Passenger assistance call in error. Reset by operator.	6516	N	4	10	
3:40pm	Jane EB	Train late entering service due to HVAC issues. Repaired.	6512	N	6	12	47
4:00pm	Finch West WB	Object at track level retrieved by operator.	6509	N	6	12	
5:06pm	Albion EB	Switch failed. No delay to service.					
8:31pm	Driftwood EB	Fault code. No delay to service.	6514	N			
	Tuesday December 16						
4:54am	Humber College EB	Guideway intrustion system failed after software update. Bypassed. Service turned back at Martin Grove.	6509	N	26	36	
5:07am	Jane EB	Fault code.	6511	N			

Finch West Line 6 Delay Log Summary December 14-20, 2025							
Time	Location	Reason	Car	Change Off	Delay	Gap	Out of Service
5:13am	Duncanwoods WB	Overspeed causing emergency braking.	6508	N			
6:06am	Sentinel WB	Train overshot platform. No doors off platform.	6504	N			
6:52am		Loss of SCADA communications. Restored at 8:14am.					
7:24am	Humber College EB	HVAC problems. Repaired by tech. One train turned at Mount Olive.	6502	N	15	19	
8:51am	Jane WB	Fault code. Train unable to proceed. Repaired by mechanic. One train turned at Norfinch, one at Tobermory.	6507	N	23	27	
9:23am	Driftwood EB	Leveling error due to loss of one compressor. Train removed from service.	6515	Y			
11:13am	Milvan Rumike WB	Emergency signal activated. No trouble found.	6504	N			
11:47am	Finch West WB	HVAC problem. Train removed from service and repaired. One train turned.	6501	N	5	15	
3:21pm	Mount Olive WB	Radio communication problems. Turnbacks at various locations. Comms restored and train operated to MSF. No changeoff available.	6503	Y	25	32	241
Wednesday December 17							
5:41am	Humber College EB	Fault codes displayed. Train picked up mechanic nroute.	6517	N			
6:51am	Norfinch Oakdale WB	Fault codes displayed. Train inspected at terminal.	6507	N	5	11	
6:58am	Jane WB	No heat in cab.	6516	N			
7:00am	Humber College EB	Fault codes displayed. Train inspected at terminal.	6515	N			
7:04am	Emery EB	Fault codes displayed. Train inspected at terminal.	6517	N			
7:13am	Milvan Rumike WB	Fault codes displayed. Train inspected at terminal.	6516	N			
7:16am	Signet Arrow WB	Fault codes displayed. Train inspected at terminal.	6508	N			
7:28am	Jane EB	No radio communication at handover platform. Delayed entering service.	6503	N	6	12	25
7:45am	Jane EB	No equipment available. Scheduled runin utilized.		N	6	12	139
9:54am	Approaching Westmore EB	Overspeed. Car reset.	6511	N	3	10	
10:17am	Finch West	Alstom techs inspecting car for fault codes.	?	N	5	12	
10:40am	Milvan Rumike	Cold cab. Turnbacks at Milvan Rumike and Signet Arrow.	6517	Y	55	62	75
12:13pm	Tobermory	One module not dispensing sand.	6505	N			
3:20pm	MSF WB	Late delivery of car by yard.	6517	N	6	12	
3:57pm	MSF WB	Train unable to move due to fault code. Repaired by tech.	6517	N	6	12	26
4:14pm	Jane EB	No equipment available			6	12	199
5:17pm	Finch West WB	Tech troubleshooting undisclosed problem	6515	N	10	20	15
5:36pm	Sentinel	Track brake error codes.	6511	N	5	15	
7:33pm	Humber College EB	HVAC malfunction. Repaired by tech.	6504	N	10	20	44
8:25pm	Driftwood EB	Unable to maintain schedule due to slow operation	6503	N	15	25	

Finch West Line 6 Delay Log Summary December 14-20, 2025							
Time	Location	Reason	Car	Change Off	Delay	Gap	Out of Service
8:34pm	Duncanwoods WB	Loss of communications. Op proceeded in emergency mode to next stop. Comms restored.	6502	N	8	18	
	Thursday December 18						
3:13am	Humber College	Water pipe burst at track level					
5:07am	MSF	Switch issues					
5:12am	Norfinch Oakdale	Hand held radio not working.	6509				
5:17am	Humber College	No movement authority	6511				
6:54am	Westmore WB	Humber College platform 1 taken out of service due to water leak. One train turned at Martin Grove.	6502	N	5	11	
7:24am	Humber College EB	Switch problem.	6516	N	3	9	
7:47am	Jane EB	No equipment available. Replaced by run-in train			6	12	135
8:09am	Stevenson EB	Emergency brake due to multiple fault codes, resolved by remedial checks.	6515	N	3	13	
10:45am	Milvan Rumike EB	Emergency brake due to multiple fault codes, resolved by remedial checks.	6515	N	3	13	
11:00am	Driftwood EB	Emergency brake due to multiple fault codes, resolved by remedial checks.	6515	N	3	13	
11:45am	Signet Arrow WB	Train out of service due to dirty cameras. Changed off.	6511	Y	10	20	
1:09pm	Sentinel WB	Misalignment error. Stop serviced in emergency mode. Train proceeded.	6515	N	5	15	
1:23pm	MSF	Switch problem. No delay to service.					
3:12pm	MSF	Hand-held radio not working in trailing car. Train out of service to troubleshoot. Deemed fit for service with on working radio.	6505	N	6	12	28
3:19pm	Humber College EB	Hand-held radio not working in trailing car. Train out of service to troubleshoot. Deemed fit for service with on working radio.	6503	N	6	12	25
6:56pm	Jane EB	No equipment available.			6	12	199
	Friday December 19						
6:36am	Finch West WB	Left side exterior camera not working	6500	N	10	20	19
7:47am	Jane EB	No equipment available			10	20	133
9:38am	Sentinel EB	Emergency brake due to overspeed. (See 9:46 entry for Driftwood below)	6508	N			
9:40am	Sentinel EB	Emergency brake due to overspeed.	6509	N			
9:46am	Driftwood EB	Train removed from service due to operator injury from previous overspeed braking (above). Replaced by trains running in to the MSF.	6508	Y	14	24	30
10:22am	Norfinch Oakdale WB	HVAC malfunction. Issue resolved.	6511	N	4	10	
10:31am	Finch West WB	Unauthorized person walked past end gate triggering intrusion detection system.	6506	N	5	12	

Finch West Line 6 Delay Log Summary December 14-20, 2025							
Time	Location	Reason	Car	Change Off	Delay	Gap	Out of Service
12:04pm	Humber College EB	Fault code triggered emergency brakes. Reset.	6513	N			
3:35pm	Driftwood	Medical incident. Turnbacks from Norfinch Oakdale and Driftwood	6506	N	154	160	
5:47pm	Jane EB	No equipment available			6	12	199
Saturday December 20							
9:18am	Sentinel	Person walking on tracks.	6513				
10:41am	Signet Arrow to Finch W	Unable to maintain scheduled headway due to missing all lights, washroom break and auto blocking tracks.	6513	N	7	10	
10:53am	Humber College EB	Passenger at track level triggered guideway intrusion detection. No delay.					
11:31am	Finch West WB	Removed from service due to gas odour. Following train advanced.	6502	N	10	20	10
11:44am	Duncanwoods WB	Emergency brake due to overspeed.	6514	N	3	13	
1:03pm	Finch West WB	Train removed from service due to cold cab. Repaired.	6505	N	10	20	88
1:35pm	Finch West WB	Cold cab. Work refused.	6500	N	10	20	13
2:47pm	Jane WB	Emergency alarm activated in error.	6511				
2:48pm	Duncanwoods WB	Emergency brake due to overspeed.	6516	N	3	13	
2:52pm	Finch West WB	Operator injured hand on washroom door. Service advanced from opposite platform.	6506	N	14	28	144
3:02pm	Finch West WB	Multiple fault codes. Technician met train enroute for repairs.	6514	N			21
5:26pm	Signet Arrow WB	Cold cab. Changed off with train running back to MSF.	6514	Y	10	20	90
10:05pm	Finch West WB	Passenger entered station via portal triggering guideway intrusion detection. No delay.					

Finch West Line 6 Delay Log Summary December 21-27, 2025							
Time	Location	Reason	Car	Change Off	Delay	Gap	Out of Service
	Sunday December 21						
8:32am	Jane EB	Train detected "non communicating object" leaving MSF. Reset and proceeded.	6507	N	5	15	
12:11pm	Jane WB	Emergency brake due to fault code, resolved by remedial checks.	6503	N	3	13	
12:30pm	Pearldale WB	Emergency brake due to fault code, resolved by remedial checks.	6503	N			
5:59pm	Milvan Rumike to Finch West	Unable to maintain headway. One train turned at Tobermory.	6511	N	8	18	
9:19pm	Mount Olive WB	Emergency brake due to door issue. Reset. No delay.	6513	N			
9:38pm	Sentinel EB	Emergency brake due to passenger pressing door button while doors closing. Reset. No delay.	6515	N			
9:49pm	Finch West WB	Slow moving train activated guideway intrusion detection. No delay.	6503	N			
	Monday December 22						
7:06am	Humber College EB	No heat in cab. Repaired by tech. Following train advanced.	6515	N	6	12	6
7:30am	Finch West WB	No heat in car. Repaired by tech. Following train advanced.	6505	N	5	11	
10:47am	Jane WB	Emergency brake due to fault code, resolved by remedial checks.	6507	N			
12:13pm	Driftwood WB	Rider lost phone between cab door and seat. Terminal supervisor retrieved phone.	6502	N	5	14	
12:56pm	Jane EB	Unable to maintain headway.	6500	N	6	15	
2:09pm	Stevenson EB	Traction major fault code. Reset.	6508	N	3	12	
2:18pm	Duncanwoods WB	Emergency brake due to overspeed. Reset by operator.	6507	N			
4:10pm	Humber College EB	Operator requested long dwell.	6513	N	7	14	
4:12pm	Humber College EB	Operator requested long dwell.	6502	N			
4:24pm	Approaching Westmore EB	Emergency brake due to overspeed. Reset by operator.	6502	N			
4:45pm	Rowntree Mills WB	Emergency brake due to overspeed. Reset by operator. Delay aggravated by poor radio communication.	6509	N	3	10	
5:21pm	Pearldale EB	Emergency brake due to overspeed. Reset by operator.					
7:42pm	Norfinch Oakdale	Brakes holding. Multiple fault codes. Train moved to yard in emergency mode by tech.	6511	Y	35	45	36
11:08pm		Storm train operated.					
	Tuesday December 23						
6:46am	Finch West WB	Loss of network recorder. Repaired by tech.	6515	N	7	17	
8:30am	Finch West WB	Operator using washroom. Following train advanced.	6515	N	7	14	7
11:23am	Humber College EB	Held for operator interview.	6500	N	3	13	
2:49pm	Humber College EB	Monitor on one side of cab is blank. To be investigated when train runs in.	6500	N	5	15	

Finch West Line 6 Delay Log Summary December 21-27, 2025							
Time	Location	Reason	Car	Change Off	Delay	Gap	Out of Service
4:07pm	Finch West WB	Operator request long dwell.	6513	N	9	15	
5:54pm	Approaching Finch West EB	Multiple fault codes. Emergency brake. Operator initially unable to reset. One train turned at Tobermory.	6506	N	16	10	
6:45pm	Finch West WB	Guideway intrusion activated. No visible reason. Reset.	6502	N	3		
7:22pm	MSF	APS failure on train running in. Reset by tech.	6504				
8:56pm	Finch West WB	Long dwell. Following train advanced.	6500	N	8	20	
9:48pm	Norfinch Oakdale EB	Emergency brake due to overspeed. Reset by operator.					
Wednesday December 24							
8:00am	Finch West WB	Guideway intrusion activated. No visible reason. Reset. One train turned at Tobermory.	6507	N	10	17	
9:40am	Martin Grove EB	Emergency brake due to overspeed. Reset by operator.	6506	N	3	10	
10:37am	Norfinch Oakdale EB	Emergency brake due to overspeed. Reset by operator.	6513	N			
8:28pm	Jane EB	Emergency brake due to overspeed. Reset by operator.	6503				
9:11pm	Finch West WB	Unauthorized person on guideway activated intrusion detection system.	6514	N			
9:50pm	Sentinel EB	Unable to maintain headway.	6504	N	15	29	
Thursday December 25							
11:25am	Finch West WB	Operator using washroom. One train turned back at Tobermory.	6512	N	5	15	
12:31pm	Sentinel EB	Emergency brake due to overspeed. Reset by operator.	6501	N			
2:04pm	Tobermory EB	Emergency brake due to CBTC test and reset.	6516	N			
7:29pm	Mount Olive WB	Multiple fault codes. Tech met train enroute.	6502	N	5	15	
8:30pm		Service operating about 49 minutes off schedule. Changeovers initiated between Westmore and Milvan Rumike. Service close to schedule by 9:49pm.					
Friday December 26							
5:24am	Highway 400 EB	Truck fouled rails. Towed at 7:26am.	6504	N	114	124	
7:28am	Jane EB	No operator available			10	20	
7:29am	Finch W to Sentinel	Radio malfunction. Service turned back at Tobermory. Radio amplifier replaced plus additional programming.	6511	N	202	212	
9:20am	Finch West WB	Multiple switches unable to move.			10	20	55
10:48am	Humber College EB	Defective switch. Maintainers unable to repair. Service turned at Martin Grove.			355	365	
11:20am	Finch West WB	HVAC problem. Repaired by tech.	6511	N	10	20	25
1:40pm	Approaching Humber Coll WB	Disabled car. Repaired by tech. Service turned back at Martin Grove.	6505	N	122	132	

Finch West Line 6 Delay Log Summary December 21-27, 2025							
Time	Location	Reason	Car	Change Off	Delay	Gap	Out of Service
2:45pm	Sentinel EB	Defective wipers. Operated to yard for changeoff.	6503	Y	10	20	91
3:24pm	Jane WB	Switch failure.	6503	N	78	89	
3:59pm	Humber College	Medical emergency. No delay to service.					
5:09pm	Finch West WB	No operator available.			10	20	392
5:22pm	York Gate	Switch failure. Switch set manually, to be repaired after service.					
6:32pm	Finch West WB	No operator available.			12	24	394
12:02am	York Gate	Switch failure. Repaired by tech.					
1:43am	Duncanwoods	Switch disturbed. Repaired by tech.					
Saturday December 27							
2:44am	Duncanwoods	Switch lost detection. Repaired.					
2:58am	York Gate	Switch disturbed. Manually cranked by crew to allow WB yard access.					
5:37am	Norfinch Oakdale	Operator not in position. Clerical error.	6506	N	5	19	
6:32am	Finch West EB	Unauthorized person at track level. Guideway intrusion activated.	6501	N	7	22	
9:58am	Humber College EB	No heat in cab. Repaired by tech.	6502	N	5	15	
12:06pm	Jane WB	Out of service train unable to enter yard due to snowbank blocking rails. Train reversed onto mainline.	6505	N	5	15	
12:19pm	Humber College WB	Train lost movement authority approaching switch. Operator unable to see switch. Train reversed clear and proceeded.	6504	N	3	13	
5:49pm	Driftwood WB	Cold car. Train run in to MSF.	6506				
8:06pm	Humber College EB	Guideway intrusion triggered by "stutter" stop of train near end gate.					

Finch West Line 6 Delay Log Summary December 28-31, 2025							
Time	Location	Reason	Car	Change Off	Delay	Gap	Out of Service
	Sunday December 28						
8:47am	Finch West WB	No cab heat. Repaired by tech enroute.	6506	N	7	17	
8:49am	Finch West WB	No cab heat. Train removed from service.	6515	Y	10	20	76
9:01am	Humber College EB	Switch problem. Platform 2 out of service for remainder of the day.	6504	N	10	20	55
9:14am	Driftwood EB	Brake problem. Tech met car enroute.	6501	N	3	13	
9:59am	Humber College EB	Switch problem. Techs drained water from switch well.	6513	N	10	20	
10:16am	Finch West WB	Sanders not working. Tech found no trouble.	6514	N	3	13	
10:35am	Rowntree Mills	Medical emergency.	6501	N	5	15	
11:20am	Finch West WB	Car removed from service due to multiple faults. Repaired by tech. Back n service WB from Sentinel at 12:05pm.	6501	N	10	20	45
2:30pm	Finch West WB	Car removed from service due to multiple faults.	6515	N	10	20	19
2:37pm	Finch West WB	No cab heat. Repaired by tech enroute.	6507	N	10	20	24
6:16pm	Westmore WB	Multiple fault codes. Changed off with train running in to MSF.	6515	Y			
6:34pm	Jane WB	Removed from service for mechanical issues.	6516	Y	10	20	78
7:30pm	Humber College	Fire alarm activated by broken water main in station. Service turned back from Martin Grove.		N	186	198	186
7:55pm	Rowntree Mills	No cab heat. Repaired by tech.	6504	N	12	24	45
8:48pm	Finch West WB	Train held for inspection by techs. Two trains turned at Tobermory.	6501	N	12	22	
10:54pm	Tobermory WB	Overspeed caused emergency brake. Reset by operator.	6513	N			
11:04pm	Jane WB	Overspeed caused emergency brake. Reset by operator.	6504	N			
	Monday December 29						
6:30am	Tobermory WB	Fault generated non-communicating object indication. Remedial checks resolved issue.	6505	N	4	14	
6:47am	Tobermory WB	Fault generated non-communicating object indication. Remedial checks resolved issue.	6504	N	4	14	
7:37am	Albion WB	Fault codes. Tech met car enroute to repair.	6515	N			
10:37am	Milvan Rumike EB	Fault code resolved by remedial check.	6503	N			
2:08pm	Mount Olive WB	Fault code.	6507	N	3	13	
3:08pm	Norfinch Oakdale WB	Train lost communication in yard becoming a non-communicating object. Moved off in emergency mode. Delay aggravated by transit priority signal.	6511	N	17	24	
5:51pm	Humber College EB	Switch problem. One train stepback mode instituted.	6516	N			
7:07pm	York Gate	Switch problem. No delay to service.					
7:21pm	Rowntree Mills WB	Several fault codes displayed. Repaired by tech.	6507	N	10	20	24

Finch West Line 6 Delay Log Summary December 28-31, 2025							
Time	Location	Reason	Car	Change Off	Delay	Gap	Out of Service
9:04pm	Finch West WB	Loss of compressor affected leveling system. Repaired by tech.	6515	N	13	20	
9:12pm	Finch West WB	Switch problem. Thrown manually. To be inspected after service.	6507				
	Tuesday December 30						
5:31am	Driftwood WB	Emergency brake caused by re-opened doors. Reset.	6501	N			
6:59am	Rowntree Mills WB	Emergency brake caused by re-opened doors. Reset.	6502	N			
7:04am	Albion EB	Emergency brake caused by re-opened doors. Reset.	6507	N			
11:35am	Westmore EB	Loss of propulsion, brake fault codes. Remedial checks performed.	6504	N	11		
7:00pm	Emery EB	Unable to open doors. Served platform in emergency mode.	6511	N	5	11	
8:37pm	Driftwood EB	Fire alarm on car, but operator found no smoke or burning odour. Car operated out of service to Finch West. Supervisor found no evidence of fire, and flashing indication disappeared from console. Car operated out of service to yard.	6506	Y	10	22	
8:49pm	Driftwood WB	Overspeed indication while train stationary. Reset.	6514	N			
9:33pm	Stevenson EB	Operator issue.	6507	N	14	26	
	Wednesday December 31						
5:51am	Finch West WB	Fault code displayed. Reset.	6500	N			
7:13am	Humber College WB	Service backed up due to switch failure.			5	20	
7:26am	Albion WB	Car overshot platform but all doors on platform. Delay aggravated by communications failures. 1 train turned at Mount Olive.	6508	N	17	23	
7:38am	Albion EB	Assisting with WB car comms issues. 2 cars short turned.	6511	N	8	14	
7:48am	Jane WB	Operator reopened doors causing fault code. Reset.	6501	N	3	9	
9:05am	Signet Arrow	Misalignment error due to spin-slide control. Remedial checks resolved issue.	6513	N	3	8	
9:17am	Humber College	Intermittent fire alarms. No smoke or fire observed. Train taken out of service.	6506	N	6	12	
9:32am	Albion WB	Misalignment error due to spin-slide control. Remedial checks resolved issue.	6503	N	3	9	
11:35am	Westmore EB	Misalignment error due to spin-slide control. Remedial checks resolved issue.	6503	N	9	16	
12:05pm	Sentinel WB	Various fault codes. Train removed from service.	6515	Y	5	15	30
12:17pm	Emery WB	Misalignment error due to spin-slide control. Remedial checks resolved issue.	6513	N	4	10	
12:38pm	Milvan Rumike WB	Misalignment error due to spin-slide control. Remedial checks resolved issue.	6513	N	4	14	
1:29pm	Sentinel WB	Fault code displayed. Reset.	6511	N	4	14	
1:29pm	Jane EB	Misalignment error due to spin-slide control. Remedial checks resolved issue.	6515	N	4	14	
1:43pm	Humber College EB	Operator unable to maintain headway.	6516	N	4	14	
3:06pm	Norfinch Oakdale EB	Misalignment error due to spin-slide control. Remedial checks resolved issue.	6504	N	4	14	

Finch West Line 6 Delay Log Summary December 28-31, 2025							
Time	Location	Reason	Car	Change Off	Delay	Gap	Out of Service
5:06pm	Humber College	No heat in cab. Repaired by tech at Finch West Stn.	6503	N	6	12	20
5:27pm	Signet Arrow EB	Sanders not working. Issue resolved by tech at Finch West.	6502	N	6	12	20
5:55pm	Mount Olive EB	Emergency brake due to overspeed. Reset by operator.	6509				
6:19pm	Martin Grove WB	No heat in cab. Repaired by mechanic.	6512	N	4	14	
7:09pm	Signet Arrow EB	Misalignment error due to spin-slide control. Remedial checks resolved issue.	6513	N	4	14	
7:11pm	Emery WB	Emergency brake due to passenger attempting to open door during departure.	6501	N	4	14	
9:02pm	Sentinel EB	Trailer bogie brake holding. Reset by operator.	6504	N	4	14	
10:37pm	Norfinch Oakdale EB	Trailer bogie unable to move. Reset by operator.	6504	N			